



Bell ATM Service, Inc.

8100 S. Akron Street, Suite 308
Centennial, CO 80112

888.772.1990 Toll Free
303.740.8370 Phone
303.740.8162 Fax
Sales@BellATM.com

Bell ATM Service, Inc. Flat Rate Repairs

Bell ATM Part Numbers

Standard prices only: See notes below

| | | | |
|------|--|--|--|
| Test | Standard test fee on any unit or component | | |
|------|--|--|--|

Board Repair

| Nautilus Hyosung | | | |
|------------------------|---|--|--|
| BrdRep:NH2500TOWER | Repair of Tranax/Hyosung 2500/MBS5000 Tower | | |
| BrdRep:NH5100TCEASSY | Repair of Hyosung 5150T Main Tower CPU | | |
| BrdRep:NH7100TCEASSY | Repair of Hyosung 7100T Main CPU | | |
| BrdRep:NHGENMB | Repair of Tranax/Hyosung Main Board (Flash only) | | |
| BrdRep:NHGENMBARM9 | Repair of Tranax/Hyosung ARM9 Main Board (Flash only) | | |
| BrdRep:NHGENMB-SRAM | Repair of Tranax/Hyosung Main Board w/SRAM failure | | |
| BrdRep:NHMULTIDISPBRD | Repair of Tranax/Hyosung Dispenser Controller Board | | |
| BrdRep:NHMULTIMB | Repair of Hyosung 1800 Main Board | | |
| BrdRep:NHMULTICORTEXMB | Repair of Hyosung 1800SE/2700CE Cortex Main Board | | |

| Tidel | | | |
|-----------------------|---|--|--|
| BrdRep:TD1000MB | Repair of Tidel IS-1000 Main Board | | |
| BrdRep:TD2000MB | Repair of Tidel IS-2000 Main Board | | |
| BrdRep:TD2000MODBRD | Repair of Tidel IS-2000 Modem Board | | |
| BrdRep:TDGENMB | Repair of Tidel IS-3000 Main Board | | |
| BrdRep:TDMULTIPRTRBRD | Repair of Tidel IS Series Printer Board | | |

| Triton | | | |
|----------------------------|--|--|--|
| BrdRep:TRGENDISP1700BRD | Repair of De La Rue SDD 1700 Dispenser Main Board | | |
| | * With Dispenser | | |
| | * Without Dispenser | | |
| BrdRep:DNCMC | Repair of De La Rue NMD CMC Board | | |
| BrdRep:DNNFC | Repair of De La Rue NFC Board | | |
| BrdRep:TR9100DISPTDMBRD | Repair of Triton TDM Dispenser board | | |
| BrdRep:TR9100DISPTDMBRD-TW | Repair of Triton TDM Dispenser board with timing wheel | | |
| BrdRep:TR9100MB | Repair of Triton 9100 Main Board (Color or Mono) | | |
| BrdRep:TR9600CPU | Repair of SS1 CPU Board - Triton 9600 | | |
| BrdRep:TR9600EXPBRD | Repair of SS4-5 Expansion Board - Triton 9600 | | |
| BrdRep:TR9600KPADDOCKBRDV | Repair of Triton 9600 Visa docking board | | |
| BrdRep:TR9600MEMMB | Repair of SS2 Memory Board - Triton 9600 | | |
| BrdRep:TR9600MODMB | Repair of SS3 Modem/Display Board - Triton 9600 w/no modem | | |
| BrdRep:TR9600MODMB-WM | Repair of SS3 Modem/Display Board - Triton 9600 w/modem needed | | |
| BrdRep:TR9600PRTRBRD | Repair of Triton 9600 Printer Control Board | | |
| BrdRep:TR9700MB | Repair of Triton 9700 Main board | | |
| BrdRep:TRFT7000PCPRISM | Repair of Triton FT7000 CPU | | |
| BrdRep:TRGENDISPMMBRD | Repair of De La Rue Mini-Mech Dispenser Main Board | | |
| BrdRep:TRGENDOCKBRD | Repair of Triton RL/FT 5000 Docking Board | | |
| BrdRep:TRGENMB | Repair of Triton RL-5000 Main Board | | |
| BrdRep:TRGENMB | Repair of Triton RL-5000 Main Board w/component level repair | | |
| BrdRep:TRGENPRTRBRD | Repair of Triton RL/FT Printer Control Board & 9100 | | |

| | | | |
|---------------------|---|--|--|
| BrdRep:TRMAKODISPMB | Repair of Triton Mako Uni-Note Dispenser Main Board (Color or Mono) | | |
| BrdRep:TRMAKOMB | Repair of Triton Mako Main Board (Color or Mono) | | |
| BrdRep:TRMULTIMOD | Repair of RT2000/5000 Modem | | |

| Tranax | | | |
|----------------------|---|--|--|
| BrdRep:TX1700MB | Repair of Tranax 1700 Main Board | | |
| BrdRep:TXC4000MB | Repair of Hantle C4000 Main Board (10.4" Color LCD) | | |
| BrdRep:TXDISPBRD | Repair of Tranax dispenser board | | |
| BrdRep:TXDISPMCDUBRD | Upgrade of Tranax dispenser mainboard from small pully to large pully | | |
| BrdRep:TXMULTIMB | Repair of Tranax 1700W & Hantle C4000 Main Board | | |
| BrdRep:TXPRTRBRD | Repair of Tranax printer board | | |
| BrdRep:TXX4000MBASSY | Repair of Tranax X4000 Main Tower CPU | | |

Cassette Repair

| Nautilus Hyosung | | | |
|----------------------|--|--|--|
| CassRep:NHGENCASS | Repair of Tranax/Hyosung 1K or 2K Cassette | | |
| CassRep:NHGENCASS3K | Repair of Tranax/Hyosung 3K Cassette | | |
| CassRep:NHGENCASS3KR | Repair of Hyosung 3K Reject Cassette | | |

| Tidel | | | |
|---------------------------|-----------------------------------|--|--|
| CassRep:TD2000CASSFUJI | Repair of Tidel Fujitsu Cassette | | |
| CassRep:TD3000CASSMCDMII | Repair of Tidel MCDM II Cassette | | |
| CassRep:TD3000CASSMCDMIII | Repair of Tidel MCDM III Cassette | | |

| Triton | | | |
|------------------------------|--|--|--|
| CassRep:TRFT7000CASSFUJI | Repair of Triton FT7000 Fuji (F510) 3K Cassette A or B | | |
| CassRep:TRGENCASS1700 | Repair of De La Rue SDD 1700 Cassette | | |
| CassRep:TRGENCASS1700MFD | Modification of De La Rue SDD 1700 Cassette | | |
| CassRep:TRGENCASSMM | Repair of De La Rue Mini-Mech Cassette | | |
| CassRep:TRMULTICASSNMD100 | Repair of De La Rue NMD 100 Cassette | | |
| CassRep:TRMULTICASSNMD100R | Repair of De La Rue NMD 100 Reject Cassette | | |
| CassRep:TRMULTICASSNMD50 | Repair of De La Rue NMD 50 Cassette | | |
| CassRep:TRMULTICASSNMD50RLCK | Repair of De La Rue NMD Cassette Reject (Locking) | | |
| CassRep:TRMULTICASSTDM | Repair of Triton TDM Cassette | | |

| Tranax | | | |
|-------------------------|---|--|--|
| CassRep:TXMULTICASSMCDU | Repair of Tranax MCDU Cassette (T or B) | | |

Dispenser Repair

| Nautilus Hyosung | | | |
|-----------------------|---------------------------------------|--|---|
| DispRep:NHGENDISP | Repair of Tranax/Hyosung Dispenser | | Excludes Drawer style Disp. Requiring note separator. |
| DispRep:NHMULTIDISP4K | Repair of Tranax/Hyosung Dispenser 4K | | |

| Tidel | | | |
|---------------------------|------------------------------------|--|--|
| DispRep:TD3000DISPMCDMII | Repair of Tidel MCDM II Dispenser | | |
| DispRep:TD3000DISPMCDMIII | Repair of Tidel MCDM III Dispenser | | |

| Triton | | | |
|--------------------------|--|--|-------------------|
| DispRep:TR8100DISPTDM50 | Repair of Triton TDM-50 Dispenser | | |
| DispRep:TR9100DISPTDM100 | Repair of Triton TDM 100 Dispenser | | Includes Cassette |
| DispRep:TRGENDISP1700 | Repair of De La Rue SDD 1700 Dispenser | | |
| DispRep:TRGENDISP1700RL | Repair of De La Rue SDD 1700 Rear Load Dispenser | | |

| | | | |
|---------------------------|--|--|--|
| DispRep:TRGENDISPMM | Repair of De La Rue Mini-Mech Dispenser | | |
| DispRep:TRGENDISPTDMEX | Repair of Extension for a Triton TDM 250 Dispenser | | |
| DispRep:TRMAKODISP | Repair of De La Rue Uninote/Mako Dispenser | | |
| DispRep:TRMULTIDISPMD100 | Repair of De La Rue NMD-100 Dispenser | | Excludes damaged plastic side panels or extensions |
| DispRep:TRMULTIDISPMD50 | Repair of De La Rue NMD-50 Dispenser | | Excludes damaged plastic side panels or extensions |
| DispRep:DNNFU | Repair of NMD 50 and 100 Note Feeder Unit | | |
| DispRep:DNNT | Repair of Note Transport Unit for NMD50 Dispenser. | | |
| DispRep:DNFR | Repair of NMD 50 and 100 Cassette Extension | | |
| DispRep:TRMULTIDISPTDM150 | Repair of Triton TDM-150 Dispenser | | Includes Cassette |
| DispRep:TRMULTIDISPTDM200 | Repair of Triton TDM-200 Dispenser | | Includes Cassette |
| DispRep:TRMULTIDISPTDM250 | Repair of Triton TDM-250- Dispenser | | Includes Cassette |

| | | | |
|-------------------------|---------------------------------|--|----------------------|
| Tranax | | | |
| DispRep:TXGENDISP | Repair of Tranax Dispenser | | |
| DispRep:TXMULTIDISPMCDU | Repair of Tranax MCDU Dispenser | | Upgrade NOT included |

Keypad Repair

| | | | |
|----------------------|--|--|--|
| KPADRep:GENKPADV | Reset Only - Keypad, Alpha-Numeric (Triton, Tranax, Hyosung) | | |
| KPADRep:GENKPADVEPPI | Repair of EPPI Keypad (Tidel,Tranax,Hyosung) | | |

| | | | |
|------------------------|--|--|--|
| Nautilus Hyosung | | | |
| KPADRep:NHGENKPADPCI | Repair of Hyosung 5100/7000/7100/7600 Keypad | | |
| KPADRep:NHMULTIKPADPCI | Repair of Hyosung 1800/5000CE PCI Keypad | | |

| | | | |
|-------------------|---|--|--|
| Triton | | | |
| KPADRep:TRGENSPED | Repair of Keypad, Alpha-Numeric, SPED, Triton | | |

LCD/Screen Repair

| | | | |
|------------------|------------------------------------|--|--|
| Nautilus Hyosung | | | |
| LCDRep:NH5000LCD | Repair of 10.4" Hyosung 5000CE LCD | | |

| | | | |
|--------------------|------------------------------------|--|--|
| Triton | | | |
| LCDRep:TRMULTILCD | Repair of Triton RT2000/RL5000 LCD | | |
| LCDRep:TRRL2000LCD | Repair of Triton RL2000 8" LCD | | |

| | | | |
|--------------------|--|--|--|
| Tranax | | | |
| LCDRep:TXC4000LCDC | Repair of Tranax C4000 LCD | | |
| LCDRep:TXGENLCDC | Repair of Tranax 1700/E4000 Color 5.7" LCD | | |
| LCDRep:TXGENLCDM | Repair of Tranax 1700/E4000 Mono 5.7" LCD | | |

Printer/Presenter/Modem Repair

| | | | |
|-------------------------|---|--|------------------------|
| Nautilus Hyosung | | | |
| PRTRRep:NH5100TPRTRASSY | Repair of Hyosung 5100T/5000XP Printer Assembly | | PCB Board Not Included |
| PRTRRep:NH7000PRTRASSY | Repair of Hyosung 7000 Printer Station | | PCB Board Not Included |
| PRTRRep:NHMULTIPRTRASSY | Repair of Tranax/Hyosung Printer Station | | PCB Board Not Included |

| | | | |
|-------------------|---------------------------------|--|------------------------|
| Tidel | | | |
| PRTRRep:TDGENPRTR | Repair of Tidel Thermal Printer | | PCB Board Not Included |

| | | | |
|-----------------------------|---|--|------------------------|
| Triton | | | |
| PRTRRep:TR9600PRTR | Repair of Triton 9600 Printer | | PCB Board Not Included |
| PRTRRep:TR9700PRTR | Repair of Triton 9700 Printer | | PCB Board Not Included |
| PRTRRep:TRGENPRTR | Repair of Triton Printer | | PCB Board Not Included |
| PRTRRep:TRRL5000PRTRPRES | Repair of Triton RL Presenter | | PCB Board Not Included |
| PRTRRep:TRRL5000PRTRTOTASSY | Repair of Triton RL/FT Printer Assembly | | PCB Board Not Included |

Power Supply Repair

| | | | |
|------------------|--|--|--|
| Nautilus Hyosung | | | |
| PSRep:NHGENPS | Repair of Tranax/Hyosung MB Power Supply | | |

| | | | |
|------------------|--|--|--|
| Triton | | | |
| PSRep:DNPS | Repair of Triton NMD 100 Power Supply | | |
| PSRep:TR9100PS | Repair of Triton 9100 Machine Power Supply | | |
| PSRep:TRGENPS | Repair of Triton 9600/Tidel Machine Power Supply | | |
| PSRep:TRMULTIPS | Repair of Triton Power Supply | | |
| PSRep:TRRL5000PS | Repair of Triton RL5000 Machine Power Supply | | |

| | | | |
|---------------|-------------------------------|--|--|
| Tranax | | | |
| PSRep:TXGENPS | Repair of Tranax Power Supply | | |

Flat Rates Do Not Include the Following:

- PCB Main Board repair or replacement
- Physical or shipping damage to any component or part of the machine
- Replacement of missing parts
- EPROM resets

ALL TRADEMARKS BELONG TO THEIR RESPECTIVE OWNER - PRICES SUBJECT TO CHANGE WITHOUT PRIOR NOTICE

© 1996-2011 BELL ATM SERVICE, INC.

Publish Date: 11/11/11

New Prices of
November 2011